UNITED STATES DISTRICT COURT SOUTHERN DISTRICT OF NEW YORK	V
THELMA SHIPPING CO. LTD.,	-X :
Plaintiff,	: 08 Civ. 01804 (PAC)
,	: ECF CASE
- against -	:
	: DECLARATION OF JOHN HICKS : IN SUPPORT OF PLAINTIFF'S
BEIJING SHOU-RONG FORWARDING SERVICE	: OPPOSITION TO MOTION
CO. LTD. a/k/a BEIJING SHOURONG FORWARDING SERVICE CO. LTD.,	FOR COUNTERSECURITY
TOTAL OLIVIOL GO. ETB.,	:
Defendant.	; _x
	-/\

- I, John Hicks, declare under penalty of perjury of the laws of the United States of America as follows:-
- 1. I am a partner in the English law firm, Waterson Hicks.
- 2. I am instructed on behalf of the Plaintiff, Thelma Shipping Co. Ltd., in this matter and am authorized to make this declaration on their behalf in relation to the alleged claim now being brought by the Defendant, Beijing Shou-Rong Forwarding Service Co. Ltd. a/k/a Beijing Shourong Forwarding Service Co. Ltd., that Plaintiff breached the charter party and is liable to Defendant for the underperformance of the vessel.
- The underlying dispute in this matter arises from Defendant's failure to pay hire in the 3. amount of \$984,891.60 to Plaintiff in breach of the charter party executed between the parties on November 9, 2007 ("Charter Party").
- 4. Pursuant to the Charter Party, Plaintiff chartered the vessel "MANASOTA" ("Vessel") to the Defendant to perform a ballast voyage from the Far East to Itaguai, Brazil to load a cargo of bulk iron ore and then carry that cargo back to China.
- 5. As is typical in the shipping world, the Charter Party is evidenced by two documents: (1) the fixture "recap" agreed to by the parties; and (2) the unsigned pro forma charter party containing the "boiler plate" language of the charter, to be adjusted/ amended/revised by the Fixture Recap
- 6. It is a well-settled principle of English law that the terms of a Fixture Recap prevail over the terms of the proforma charter party. See Glyn v Margetson (1893) AC 351 at p 358 - House of Lords; The Brabant (1965) 2LLR 552 at p 552-554; and The Starsin (2000)1 LLR 85 at p 89-90.
- Here, the Fixture Recap expressly provides "WHERE THE VESSEL REMAINS AT ANCHORAGE, IN PORT OR IDLE FOR AN EXTENDED PERIOD IN COMPLIANCE WITH CHRTRS' ORDER/INSTRUCTIONS, AND THIS CAUSES FOULING OF THE

HULL OR UNDERWATER PARTS, OWNERS SHALL NOT BE RESPONSIBLE FOR SUCH FOULING OR ANY VESSEL UNDERPERFORMANCE CAUSED BY SUCH FOULING. THE COST OF CLEANING AND PAINTING THE HULL OR UNDERWATER PARTS, AND THE TIME SPENT DOING SO, SHALL BE FOR THE CHARTERERS' ACCOUNT. See Fixture Recap, p. 4 annexed to the Verified Complaint as Exhibit "1."

- 8. This provision in the Fixture Recap repeats clause 102 of the proforma charter party. but in doing so deliberately excludes the definition of "extended period" which in the proforma is stated to mean 20 days.
- Soon after the Plaintiff took redelivery of the Vessel from its prior charter, the Vessel 9. took bunkers at Singapore on November 9-10, 2007, at which time the underwater areas of the Vessel were cleaned so that on sailing all underwater areas were free of growth.
- The Vessel then ballasted across the Indian Ocean and South Atlantic to Brazil where she was obliged to wait in a warm water port, pursuant to the Defendant's instructions, for some 18 days in order to load the cargo.
- 11. The Defendant contends that the Vessel was delayed in a warm water port for 18 days which caused the fouling of the hull. It further admits that the fouling caused the alleged underperformance. See Defendant's Memorandum of Law in Support of Motion for Countersecurity, p. 4.
- 12. Thus, even a cursory application of the undisputed facts to the law (i.e. the contract), which states that Owners are not responsible for fouling or underperformance caused by fouling, reveals that Defendant does not have a prima facie valid claim against Plaintiff.
- Defendant makes the outlandish argument that notwithstanding the clear language of the Charter Party that somehow Clause 102 is controlling.
- 14. This argument is unavailing. Under English law, like U.S. law, the language of a contract should be given its plain meaning.
- 15. Based on my examination of the facts and the relevant case law, under English law, Defendant's claim for underperformance would be precluded by the precise wording of the Charter Party.
- 16. Moreover, it is well-established under English law, that where bottom growth accumulates by reason of a vessel following charterers' orders and reduces the Vessel's performance that this shall not constitute a defect in the vessel entitling Charterers to make a deduction in hire. See The Rijn [1981] 2 LLR 267 and the Pamphilios [2002] 2 LLR 681.
- 17. Defendant's counterclaim hinges on clause 102 of the proforma charter party, which was expressly overridden by the Fixture Recap.

- 18. Therefore, as shown above, Defendant's counterclaim for underperformance has no basis under English law, and Defendant has failed to show that it has a prima facie valid maritime claim against the Plaintiff.
- 19. Defendant's argument under Clause 1, namely that Plaintiff failed to maintain the ship by allowing bottom growth to accumulate while the vessel was delayed at Itaguai, also has no basis in law or fact.
- 20. Particularly, Plaintiff has no claim under Clause 1 because the Vessel was following Defendant's orders and instructions by waiting at a warm water port for an extended period of time and the accumulation of bottom growth in such circumstances is inevitable.
- There are no practical steps to prevent the accumulation of growth that can be taken by Plaintiff/Owners in such circumstances.
- 22. The Defendant has not even indicated in what respect the Plaintiff failed to comply with this clause - the clause merely requires Plaintiff to take reasonable steps within a reasonable time to rectify any inefficiency. See Snia v. Suzuki [1924] 17 LLR 78.
- 23. Plaintiff took adequate steps to prevent the accumulation of marine growth. The vessel, being of relatively new construction, had anti-fouling paint applied to her underwater areas which was still well within warranty.
- 24. The accumulation of marine growth where a vessel is delayed, particularly in a warm water port, is not a matter dealt with by routine maintenance of the vessel.
- To remove marine growth the vessel has to be stopped and taken out of service and 25. cleaned.
- In circumstances where the need for the cleaning arises as a direct result of the charterers' (Defendant's) orders, as was the case here, either the Vessel should not be placed off-hire in the first place or alternatively Plaintiff are entitled to an indemnity for the full extent of any loss arising. See Island Archon [1994] 2 LLR 227. According the clause 1 "argument" raised by Defendant has no merit whatsoever.
- In my respectful opinion, the counterclaim device has simply been raised by Defendant in an attempt to cause inconvenience and delay to the Plaintiff, the claim and/or defense thereof being entirely spurious and without merit. Thus, the Court is respectfully requested to deny Defendant's Motion for Countersecurity.
- 28. Finally, the Defendant has still failed to serve a Defence Submission in the London Arbitration. Claim submissions were served by the Plaintiff on March 17, 2008 and the Tribunal ordered that the Defendant should serve a Defence by no later than April 17, 2008. The Tribunal has now issued a further Order against the Defendant that any Defence must be served by May 5, 2008. I submit that the Defendant's failure to serve a Defence to date reflects the frivolous nature of its Counterclaim (and Defence) in general.

- 29. In light of the foregoing, we submit that Plaintiff has not and cannot bring a valid counterclaim for underperformance under English law.
- Defendant should not be allowed to subvert the purpose of Rule B attachment by concocting counterclaims in the hopes of gaining leverage over the Plaintiff.
- 31. The underperformance claim is simply frivolous on its face and has, in my opinion, no prospect of success in London arbitration or at all and should never have been ever intimated and should be withdrawn.
- Furthermore, even presuming that the underperformance claim has any merit, which is denied, the calculations used therefore are incorrect. Defendant has failed to reasonably estimate its damages. Therefore, at the very least, if the Court does not deny the motion for countersecurity on the basis that Defendant has a frivolous claim, it should still refuse to order countersecurity because as a matter of quantum. Defendant has no remaining claim. Particularly, Defendant has arithmetically miscalculated its claim such that it is already fully secured (by way of deduction from hire). See Exhibit "1."
- 33. The distance steamed Itaguai/Singapore was 9,074 miles and Singapore/Majishan was 2,160 miles, a total of 11,234 miles. This is 241 miles more than Defendant's estimate.
- Defendant has the WNI report recording the distances steamed. See Exhibit "2."
- Therefore, even assuming arguendo that the Vessel would make a speed of 13.5 knots in all weather and current conditions (which is clearly not correct in any event) the steaming time allowed for 11,234 miles at 13.5 knots is 34.672839 days. The time actually used was 39.75 days.
- Defendant also made an arithmetical error on the sailing time from Singapore the vessel sailed at 1500 GMT, nor 1400 GMT. Therefore the time lost, (assuming that the claim exists in the first place, which is denied) would be 5.077161 days, not 5.862655 days. Taking this into account, the deduction from hire, absent proper assessment of the Vessel's performance given bad weather, adverse currents, etc, should be \$888,503.17 gross or \$855,184.30 net of credit which should be made for 3.75% commission.
- Defendant has already deducted \$1,025,964.63 from the hire owned to Plaintiff, an over-deduction of \$170,780.33.
- Furthermore, although Defendant deducted the time spent maneuvering into and bunkering at Singapore in its calculation of the steaming time used, it has failed to take account of bunker consumption through this time. Defendant has the WNI calculations which record this amount to be 32.8 mt IFO (US \$16,498.40) and 12.3 mt MDO (US \$9,102.00). Based on these numbers, Defendant over-deducted another \$25,600.40.
- 39. Finally, Defendant's calculations are inherently unreasonable because they do not take account of the adverse weather conditions experienced during the voyage from Itaguai

- to Singapore and Majishan. The WNI report sets out the many instances of weather exceeding Beaufort 4 and adverse current. All of Defendant's calculations are based on the concept that the Vessel experienced solely good weather and sea conditions throughout the entire voyage, a fact which is demonstrable false.
- 40. Defendant has no claim for underperformance (as discussed earlier). However, even if the claim did exist, which Plaintiff denies, using Defendant's own method of calculation, it has over-estimated its claim.

Executed on April 28, 2008 in London, England.

John Hicks

EXHIBIT "1"

SOLICITORS

130 Fenchurch Street London EC3M 5LY

Telephone : 020 7929 6060 Facsimile : 020 7929 3748 Email: law@watersonhicks.com

Web : www.watersonhicks.com

FACSIMILE TRANSMISSION

DATE : 28 March 2008

PAGES: 2

TO Winter Scott Glenn Winter ATTN REF GDW/ln/364/29 FAX 020 7726 2371

FROM:

John Hicks

REF

JWH/WB/1042-31

"MANASOTA" - C/P dated 9.11.07

Thank you for your fax of 20th March.

As you will appreciate your clients' calculations are incorrect.

1. As a starting point, the vessel's underwater areas were cleaned at Singapore on 9th/10th November 2007 before performing the ballast voyage to Brazil. That ballast voyage was then performed in excess of the Charterparty speed and with bunker consumption below the Charterparty warranty. It was only following the delay in loading at Itaquai that the vessel's performance speed and consumption reduced below the Charterparty warranties. When the vessel arrived back at Singapore on the return laden voyage to bunker once more she was inspected underwater and found to be fouled. This was the obvious effect of the delay in loading at Itaguai.

You have argued, as have your New York attorneys, that Clause 102 of the Charterparty provides that a delay at a loading port must exceed 20 days before Charterers become responsible for fouling. As we explained during the course of our telephone conversation of 19th March, you have omitted to take account of the recap which removes that 20 day minimum criteria and merely provides that where the vessel remains at anchorage for an extended period in compliance with Charterers' orders and this causes fouling Owners shall not be responsible for the fouling, underperformance or the cost of cleaning. It is trite law that the terms of the recap prevail over the terms of the pro forma Charterparty. The Singapore surveys place the cause of the fouling in such clear relief that there really should be no argument about this case and your clients should pay the sum wrongfully withheld without further delay. Any other approach on their part is frankly an abuse of process.

CONFIDENTIALITY NOTICE

The contents of this fax and any attachments are confidential, for the use of the addressee only and may be legally privileged. If you are not the intended recipient of this fax, or the employee or the agent responsible for delivering it to the intended recipient any copying, distribution or other action taken or omitted to be taken in reliance upon it is prohibited and may be unlawful. Please return the fax and any attachments to us and destroy any copies which may have been made, Thank you.

J.W. Hicks, M.J. Wisdom, B.M. Isola, M.S. Aspinall, T.D. Baker, A.S. Ridings

- 2. We have seen the assertion raised by your New York correspondents that Owners were in breach of Clause 1 of the Charterparty "by allowing underwater growth to accumulate". As you know, this is an entirely forlorn argument: there was nothing the Owners could have done to prevent the accumulation of underwater growth while following your clients' orders and waiting at Itaguai.
- 3. Without prejudice to this, the basis of your clients' calculations is incorrect both arithmetically and as a matter of principle. The distance steamed Itaguai/Singapore was 9,074 miles and Singapore/Majishan was 2,160 miles, a total of 11, 234 miles. This 241 miles more than your clients' estimate. You have the WNI report recording the distances steamed. Even if we adopt the simplistic approach taken by your clients of assuming that the vessel will make a speed of 13.5 knots in all weather and current conditions (which is obviously not correct either) the steaming time allowed for 11,234 miles at 13.5 knots is 34.672839 days. Time actually used was 39.75 days: again your clients have made an arithmetical error on the sailing time from Singapore the vessel sailed at 1500 GMT, not 1400 GMT. Therefore the time lost according to your clients' calculation should be 5.077161 days, not 5.862655 days. The deduction from hire should, absent proper assessment of the vessel's performance given bad weather, adverse currents etc., should thus be US\$888,503.17 gross or US\$855,184.30 net of the credit which should be made for 3.75% commission. Instead your clients have already deducted US\$1,025,964.63, an overdeduction of US\$170,780.33 which alone almost entirely extinguishes the purported counterclaim raised by your clients of US\$181,604.53.
- 4. Although your clients have deducted the time spent manoeuvring into and bunkering at Singapore from their calculation of the steaming time used, they have omitted to take account of bunker consumption through this time. You have the WNI calculations which record that this amounted to 32.8 mt IFO (US\$16,498.40) and 12.3 mt MDO (US\$9,102.00). Again adopting this very simplistic approach your clients have overdeducted US\$25,600.40. Taking this together with the overdeduction of time taken explained above, your clients have already overdeducted US\$196,380.73, more than the total amount of their counterclaim of US\$181.604.53.
- 5. One then has to take account of the adverse weather conditions experienced during the voyage from Itaguai to Singapore and Majishan. The WNI report sets out the many instances of weather exceeding Beaufort 4 and adverse current. In spite of this your clients' calculations presumed the vessel experienced good weather and sea conditions throughout the entire duration of the voyage.

In conclusion therefore even before taking into account the weather and current conditions, your clients do not have a counterclaim on any basis. They have deducted from hire more than the maximum amount of any possible counterclaim even if they had no liability for the fouling of the vessel's underwater areas, which is obviously denied. Your clients cannot therefore be entitled to further countersecurity since they will be doubly secured in respect of the same claims.

We trust this is clear and that you will advise your New York attorneys accordingly.

Finally we confirmed to you that our clients would accept a bank guarantee from a first class London bank rather than leaving your clients' funds subject to attachment in New York. You have not responded to us upon this.

Yours faithfully,

WATERSON HICKS

hater Uth

EXHIBIT "2"



WEATHERNEWS INC. Global Center Епай: Улю-музувавроп@илфорг

Voyage Evaluation Report

Vessel Name: MANASOTA (9HDF8) Prepared for CARDIFF MARINE INC

ARRIVAL:

WNI Route Number: 2007111233

December 6, 2007

DEPARTURE:

SINGAPORE

Chartered

November 19, 2007 01:30 (GMT) December 5, 2007 15:30 (GMT)

ITAGUA:

Voyage No:

Ship Type:

BULK CARRIER

Voyage Type: Cargo: On deck:

Hole:

Loading Condition: Ballast

	CE	ïΥ	

X Oceanrouteing with or without Onboard Routing System Performance Monitoring Heavy Weather Advisory

SERVICE WITH

x Performance Speed Evaluation Speed & Bunker Analysis Route Comparison Analysis

VOYAGE SUMMARY:

1	Route selection	The vessel sailed along the recommended route.
	Schedule	Required ETA scheduled before departure: N/A
:		Actual Time of Arrival: December 5, 2007 15:30 (GMT)
i		
	Voyage Leg	Speed Performance Bunker Performance
	SINGAPORE to ITAGUAI	Performed (No Time Lost) 156.64 MT F.O. Under-consumed
	SINGAL ONE TO THE BOOK	1.86 MT D.O. Under-consumed
Ţ	DUTE COMPARISON ANALYSIS:	
•	No comparison is provided.	

Your Local Contact Office Weathernews Italia S.p.A. Viz Polestro, 6, 20121 killana, Italy Teh +39-02-76-01-32-75 Frog: +30-02-76-02-8021 Small vp_ite@wnl.com :



Performance Speed Evaluation

Vessel Name: MANASOTA

Prepared for

CARDIFF MARINE INC

WNi Route Number: 2007111233

Date:

December 6, 2007

DEPARTURE: ARRIVAL:

SINGAPORE

ITAGUAL

November 10, 2007 01:30 (GMT) December 5, 2307 15:30 (GMT)

SINGAPORE to ITAGUAI

Entire Voyage Analysis

Distance Sailed Time en Route Average Speed Weather Factor Current Factor

Performance Speed Charter Party Speed

8999 Miles 614.0 Hours 14.7 Knot(s) -0.5 Knot(s) 0.0 Knot(s)

> 15.2 Knot(s) 15.0 Knot(s)

Good Weather Definition:


Wind force Beaufort Force 4 and seas Douglas Sea State 3 (1.25m max wave height) or less for over half the day, and non-adverse average daily current.

Remarks:

Weathernews began providing ship routing service on November 13.

Route Selection:

The vessel sailed along the recommended route.



Speed and Bunker Analysis for Chartered Vessel

This calculation is based on the information obtained from the Mester/Vessel operator applying allowed time for consumption calculations. It will be updated upon receipt of corrections of Charlet Party information or additional data of ship positions, departure/arrival information.

Vessel Name: MANASOTA

WNFRoute Number: 2007111233 December 6, 2007 Date:

SINGAPORE to ITAGUAL

Performance Speed Systochion


Distance Salled	:	8999	Miles
Time en Route	:	814.0	Hours
Average Speed	;	14.7	Knot(s)
Weather Factor	;	-0.5	Knot(s)
Current Fector	:	9.0	Knot(s)
Perforcance Speed	-	15.2	Knot(s)

	Departu	re BROB	Arrival		Bunker Consume	
Voyage Leg	F.O. IMT	D.O. [MT]	E.O. [MT]	D,O, [MT]	F.O. [MT]	DO [MI]
SINGARORE to ITAGUAS	3858.70	193.00	2129.60	180,40	1529.10	12.60

Charter Party Terms:

It is understood that the Charter Party Speed is about 15.0 knots on 59.94 M/T fuel oil and 0.51 M/T diesel oil per sailing day. Allowing 0.5 knots and 5% consumption for the term 'about', an effective speed of 14.5 knots, 62.94 M/T finel oil and 0.54 M/T diesel oil have been used in the following exiculations.

1. SPEED CALCULATIONS



2. CONSUMPTION CALCULATIONS

FUEL OIL [MT]

62,94 Warranted Consumption (5% upward):

 $(642.8 / 24 \text{ Hours}) \times 52.94 = 1685.74$ Calculated Consumption ...

1529.10 Bunker Consumed on Passage

= -156.64 1529.10 - 1685.74 Under-consumed

DIESEL OIL [MT]

0.54 Warranted Consumption (5% upward) :

14.46 $(642.8 / 24 \text{ Hours}) \times 0.54 =$ Calculated Consumption 1260 Bunker Consumed on Passage -1.86

12.50 14,46 Under-consumed

156,64 MT Fuel Oil Under-consumed MT 1.88 Diesel Oil Under-consumed

Voyage Summary Report

WNI Route Number: 2007111233

December 6, 2007 Duke:

> Operator: CARDIFF MARINE INC MANASOTA

103.9E November 10, 2007 01:30 (GMT) 12 Departure: SINGAPORE Arrival: ITAGUAI Distance: 8999 miles

7.4.	1			
23.28	43.9W	December	6,2007	15:30 (GMT)
Tanga En	Time Eproute 614,0 hours	Ohours Av	rerage Sp	rs Average Speed; 14.7 knots

LON CMT	ļ						
LON	SURFA	SURFACE WIND	COMBINED WAVES	- BNOING	ROS	DAI.	DAILY CONS.
103.9B	ã	SPEED BEAUFORT PRIMARY	PRIMARY HEIGHT	25.0	F.D. M.D.D.	.a.	M.D.O.
103.9B 3.130 3.200 101.672 356.0 598.8E 4:00 5.900 101.672 356.0 598.8E 4:00 5.900 97.00E 3.500.5 598.8E 3.00.5 35.00E 4.200 4.210 97.00E 3.500.5 598.8E 3.00E 3.500.7 35.00E 5.00E 5.00E 3.00E 3.500.7 35.00E 5.00E 5.00E 3.00E 3.0	_	FORCE	DIR (M)		(M/T) (M/T)	T) (M/T)	2! 3: 3:
103.4E	-	:		9	2	103.00	_
98.45 4:00.5 5.964 97.048 360.5 69.8 42.048 36.0.5 69.8 42.048 36.0.5 69.8 42.048 36.0.5 7.048 36.3.7 80.343 67.642 320.4 80.048 5.062 339.1 360.2 5.062 5.062 5.062 339.1 360.2 360	3	1	11K 0.1	45,2	3652,44 192	192.90 60	1.0
93.13 93.13 93.13 93.13 93.13 93.13 93.13 93.13 93.13 93.13 93.13 93.13 93.13 93.13 93.04 93	- 40 - 10	^		. 84.2 3593.00	L	192.40 59.4	8,0
10 15 15 17 17 17 17 17 17	<u>]~</u>	7	3.1	85.3	161 00. 1528	90 59.5	
04.7E 5,00 2.395 93.47k 309.7 90.00 5,955 79.06k 339.1 76.45 6.00 8.955 74.102 339.1 76.45 6.00 8.955 74.102 357.9 357.6 355.32 357.6 355.32 357.6 355.32 357.6 355.32 357.6 357.6 355.32 357.6		200	8.8 NS8	85.2 3473.00	\perp	191.40 60.0	0.5
80. dg 6.10	12.9 H 15	-	8-K N96	215.2	D411 00 190	190.90	I
76.45 6.10 8.965 74.102 351.2 76.45 7.10 12.605 69.26 350.3 65.53 7.10 16.085 64.478 352.9 60.22 8.10 15.665 59.345 381.8 59.10 21.665 59.345 381.8 7.10 12.60 52.065 59.345 382.9 7.11 31.00 21.055 42.375 384.9 77.12 9.10 21.055 42.375 385.8 77.45 10.00 35.789 16.889 77.45 10.00 35.789 16.889 77.45 11.00 35.789 16.889 77.48 11.00 35.789 16.889 77.48 11.00 35.789 16.889 77.48 11.00 35.789 16.889 77.80 11.00 35.789 16.889 77.80 11.00 35.789 16.889 77.80 11.00 35.789 16.889 77.80 11.00 35.789 16.889 77.80 11.00 35.789 16.889	<u>'</u>	*	9.2	1 15.23348,50		190.40 60.0	į
70. 02 7.10 12.608 69.56% 360.1 65.53 7.10 16.088 66.778 351.9 60.23 8.10 15.665 59.345 351.9 55.12 8.10 22.055 54.59% 365.9 49.38 8.100 22.055 54.59% 369.9 43.12 9.100 28.065 42.375 360.7 31.08 10.10 35.739 30.528 35.6.8 37.00 35.739 30.528 35.76 35.58 11.00 35.739 10.24E 357.0 4.00 35.739 4.00% 355.1 4.00 35.759 4.00% 355.1 11.2% 12.00 35.759 4.00% 355.1 11.2% 12.00 35.759 4.00% 355.1 11.2% 12.00 35.759 4.00% 355.1	4. 7 SE 1.4	*	55% 2.5	85.2	3265,00 189	189,90 63	କ୍ ବ୍
65.53 7:00 16.083 66.47E 351.9 60.23 8:00: 19.665 59.395 351.8 55.10 8:00: 22.065 59.395 351.8 49.38 8:00: 25.399 40.355 359.9 74.31 9:00 25.399 36.435 350.7 37.12 9:00 35.399 30.52E 350.6 37.45E 10:00 35.299 23.66E 357.6 10.5E 11:00 35.789 16.896 357.7 4.00 12:00 35.789 4.000 357.7 11.20 12:00 35.789 4.000 355.7 11.20 35.789 4.000 355.7	15. 6.858 16.81	4	<u>т</u> 9€ 2.8]	18.2 3223,00. 189,40	59.5	5 E
60.22 R:00: 19.665 59.596 351.8 55.10 8:00 22.055 59.596 36.9 49.38 8:00 28.065 42.355 359.9 74.12 9:00 28.065 42.315 350.0 31.08 10:00 35.299 30.528 357.0 10.56 11:00 35.789 16.296 347.9 3.58 11:00 35.789 16.296 347.9 4.00 35.789 4.00 35.78 11.20 35.789 4.00 35.78 11.20 35.789 4.00 35.78 5.58 11:00 35.789 4.00 355.78 11.20 35.789 3.318 36.6	24.7 533 13	4	55W 3.2		85.23163 30, 186	188.90 59.7	
## 10 22,065 54,694 349.5 349.5 349.5 349.5 349.5 349.5 349.5 349.6 349.5 349.6 349.5 349.6 349.6 349.5 349.6 349.	15.2 GSE XZ	*	25 ¥25	1 65.2 5101	101.30 189.	59.5	50 10
49.38 8.007 25.394 40.352 354.9 43.12 9.00 28.065 42.375 365.0 37.12 9.00 30.063 42.375 365.0 31.08 10.00 35.235 23.635 357.6 37.28 11.00 35.235 16.895 347.6 35.58 11.00 35.749 16.895 347.6 3.55 11.00 35.749 16.895 347.0 3.55 11.00 35.758 4.000 355.1 4.000 355.1	14.6 ₹ 32	-	58W 2.6	85.23041	187 00, 120	96 96	- C
43.12 9:00 28.065 42.375 360.7 37.12 9:00 30.708 36.315 351.0 31.08 10:00 35.238 23.65 37.44 11:00 35.238 23.65 35.52 11:00 35.789 16.895 4.00 35.78 4.00 357.9 4.00 35.78 4.00 357.9 11.20 34.77 11.374 364.6 35.50 12:00 35.78 4.00 355.1	14.0 NR 19	m	85W 3.2	ļ	85.2 2982.30 104	189.48 59.	50
17.1E 9.6P 30.708 36.41B 351.0 31.0B 10.60 33.189 36.5E 336.8 74.4E 10.00 35.238 23.6E 357.6 10.5E 11.00 35.789 16.895 347.6 3.5E 11.00 35.789 4.009 357.9 4.00 12.00 35.78 4.009 355.1 11.20 34.078 11.174 364.6	15.0 MZ	N N	2	5 88.2	88.2 2520.30 196	146.90 59.5	5.0
31.08 10:00 33.189 30.52B 336.8 74.48 10:00 35.238 23.65B 353.6. 15.28 11:00 35.789 16.89% 347.6 3.58 11:00 35.789 4.009 355.1 4.00 35.18 4.00 35.78 4.009 355.1 11.20 12:00 35.18 4.009 351.6	14.63 KNW 10	·	SH	65.2.2	85.2 2360,60,186	186.40 59	2.0
74.48 10:00 35.235 73.06E 357.6 15.28 11:00 35.789 16.894 347.6 10.5E 11:00 35.789 16.894 347.9 3.5E 11:00 35.718 3.21X 347.9 4.094 12:00 35.718 4.00M 355.1 11.2M 12:00 35.759 13.794 354.6	14.0 6.5W 22	9	2.5	2	2 2738 .60 105	<u>위</u>	
15.2k 11:00 35.789 16.8kg 347.6 10.5k 11:00 35.789 16.8kg 347.9 4.0k 12:00 35.55 14.00W 361.6 11.2k 12:00 35.55 14.00W 361.6	14.9 ENS 18	4	364	5	28738,89 185	9	
10.5E 11.00 35.759 10.4E 337.0 4.00 12.00 35.158 4.00W 355.1 11.2M 12:00 35.158 1.17W 364.6 12.0W 12:00 12:05 13.00W 361.6	8 161	5 1 0	3.4 	9 35.2 2676	œ.	164.99	50.15 10.15
3.58 11:00 35.718 3.718 347.9 4.00 12:00 35.158 4.000 355.1 11.20 12:00 34.075 11.770 364.6 10.00 12:00 12:055 18:008 361.6	14.0 8 3.0		88# 3.	85.22	<u>ج</u>	9	į
11.2W 12:00 35.158 4.00W 355.1 11.2W 12:00 34.075 11.17W 564.6	14.5 53W 1 11	4	8.9W 2.0	95.2	2567.50 78	187,90, 59	1
11,2M 12:DO 34,075 11,17W 364,6	14.0 KMK	ra un	5.1 1.1	\	85.2 2495.50 18	183,40 59	59.5
10.08 12:00 12:655 18:00H 361.6	15.2 M	2	BK 1.4	0 85.2 2435	힒	182.90 59.	<u> </u>
	15.1 N 1.21	4	-i	2 85.32	85.32376.30 18	182,40 59	59.5
T FITHER	15.1 NWW 18	2	-i	9 85.2.2	85.2 2314.30 101	힣	59,5, 0.5
11.08 13.00 28.839 30.7085 341.3	14.2 WIN 1.		asw 1.	4 85.2 2254	254,00 181	97	59.0



кероп
Summary
Voyage

WNI Route Number: 2007111233

December 6, 2007

Dale

		-	-						_	_
AVEIKMAE	DAILY CONS.	000	٠.	(M/T) (M/T)	19 0 St 19 19 19 19 19 19 19 19 19 19 19 19 19		3 H O S S S S		200	
REPORTED VESSEL DATA	REGINE	002	- >		26 3 3 34 9 9 1 1 8 0 4 0	40.4 CD. 25.4 CD. 26.4 CD. 26.	85, 251, 33, 30 180, 40	4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	177. APT 140. 476	
1200 GMT WEATHER	SEVANO GENERAL COMPLETE VANOES	CONTRACT TO STATE OF THE PARTY	DIR SPEED BEAUFORT PRIM	AKTST FORCE DIR (M)		895 3 2 2 E 395			_	· · · · · · · · · · · · · · · · · · ·
Valva			DISTANCE SPEED 1	E E E E E E E E E E E E E E E E E E E	7	357.6 14.9 895	ı	374.3 15.4 MG	0 00	
the rate of the	TXM GMF UK	DAILY POSITIONS	NO.	<u>.</u>		26.388 36.85%		23,639 43,04%	ı	-
	REPORTED POSITIONS			NO.		20 30 14 AN. 14 DO		23.48 43,5N 14:00	*	23.28 43.9K 15:304
	₹		1	3160		10.00	12/4	12/5 23		12/5 23

MANASOTA

December 6, 2007

Date

---- er roos incomente sandar ibika

To: ITAGUAL


From: SINGAPORE


CARDIFF MARINE INC


Number of Days of Wind (Beaufort Force)


	Total	3.50	4.50	7.50	00.6	2.00	25.80
	ů,				:		
	G.			. !	į		
.]	8	·	***************************************		1		
	<u></u>					 	
	9		0.25]]		0.50
	ç,	05.0		ا ا	0.75	0.75	4.75
	4	1.25	1.75	3.75	4.50	0.50	4.75 11.75
	6		0.25	2.25	2.00	0.25	
•	2	0.25	0.25	0,25	1.25	0.50	2.50
	•	0.25	0.25		0.50		00.1.
	D	0.25	- 				0.25
		Head	Вом	Веага .	Quarter	Follow	Total 0.2


		٠.					. [\ 	ŀ	ľ	
v.			eo	4	5	j	~	80	a	ς,	Totaí
		1,75	1.50								3.25
1.00	1.75	7,25	6.25						<u>-</u>	÷	16.25
0.25	1.50	2,00	05.0				1		-		4,25
	06.5		0.25			: [1.75
									- li		
1.25		11.00	B.50					-			25.50
			1.76	1.76	1.76	1.76	1.76	1.75 1.50 6.25 1.75 2.00 0.50 1.50 2.00 0.25 4.75 11.00 0.50	1 2 3 4 5 6 7 8 1 1.50 1.75 1.50 1.50 1.75 1.50 1.50 1.50 1.50 1.50 1.50 1.50 1.5	1,75 1.00 B 50	1.75 1.50 4.75 6.25 8 7 8 9 >9 1.75 1.50 9 3.50 9 3.50 9 3.50 9 3.50 9 3.50 9 3.50 9 3.50 9 3.50 9 3.50 9 3.50











WEATHERNEWS INC. Global Center Етай блачоуадаграф<u>о</u>модова

Voyage Evaluation Report

Vessel Name: MANASOTA (9HDF8) Prepared for CARDIFF MARINE INC

WNI Route Number: 2007122212

February 18, 2008

DEPARTURE: ARRIVAL:

ITAGUA! SEILUN

December 23, 2007 14:00 (GMT) February 2, 2008 03:00 (GMT)

Ship Type:

BULK CARRIER

Voyage No: Voyage Type: Chartered

Leading Condition: Loaded

Cargo: On deck: ΝĒ

159700 MT ABT IRON ORE IN BULK Hold:

SERV	TV	DE
יאתר	11	~~

į	🗓 Oceanrouteling with or without Onboard Routing System
į	Performance Monitoring Heavy Weather Advisory
	Heavy Weather Advisory

SERVICE WITH

🔀 Performance Speed Evaluation 🗶 Speed & Sunker Analysis Route Comparison Analysis

VOYAGE SUMMARY:


Charles and the officer		
Route selection	The vessel sailed along the recommend	Mended foule.
Schedule	Required ETA scheduled before de	perture: N/A
i		· · · · · · · · · · · · · · · · · · ·
L	Actual Time of Artival:	February 2, 2008 03:00 (GMT)

Voyage Lag	Speed Zerfannizade	Banker Performance
ITAGUALIO BEILON	Underperformed (74.9 Hours Lost)	120.64 MT F.O. Over-consumed
į	Ĺ	0.38 MT D.O. Over-consumed

ROUTE COMPARISON ANALYSIS:

- 1						
:	NO D	פתחונ	пеоп	18	provided.	

Your Local Contact Ciffice Weathernews later S.p.A., Yie Resum, B. 20121 Mans, Indiy 761 +120-02-75-01-82-75 Fax: +26-02-76-02-8021 तिव्यवी पर्याक्षियाम् २००५



Performance Speed Evaluation

(1 of 2)

MANASOTA Vessel Name:

CARDIFF MARINE INC Prepared for

WNI Route Number: 2007122212

Date; February 18, 2008

DEPARTURE: ARRIVAL:

JTAGUAL BERLUN

December 23, 2007 14:00 (GMT) February 2, 2003 03:00 (GMT)

ITAGUAI to BEILUN

	Good Weather Analysis	Entire Voyage Analysis
Distance Sailed	594. Miles	11134 Miles
Time en Route	48.0 Hours	938.0 Hours
Average Speed	12.4 Knot(s)	11.9 Knot(s)
Weather Factor	0.0 Knot(s)	-0.5 Knot(s)
Current Factor	C.2 Knot(s)	-0.1 Knot(s)
Performance Speed Charter Party Speed	12.2 Knot(s)	12.5 Knot(s) 14.0 Knot(s)

Good Weather Dafinition:

Wind force Beaufort Force 4 and seem Douglas Sea State 3 (1.25m max wave height) or less for over half the day, and non-adverse average daily current.


Remarks:

Good Weather Analysis

A good weather day is defined by Meathernows as being the period between consecutive daily moon positions where the analyzed weather conditions experienced by the vessel did not exceed the above mentioned good weather definitions.

The following days were analyzed and determined in excess of good weather definitions:

December 24 to January 16, 18 to 28, 22 to 24, January 25 to Pebonary 2



Performance Speed Evaluation

Vessel Name: MANASOTA

CARDIFF MARINE INC

WNI Route Number: 2007122212

Date: February 18, 2008

Notes:

Prepared for

The following time and distance has been excluded from the Performance Speed Evaluation due to transit through Singapore strait:

Date/Time Duration Distance 01/24/08 04002-01/24/08 20002 16.0 Mours 100 Miles

The quantity of bunkers consumed on passage excludes 32.80 km of fuel oil and 12.30 km of dissel oil that was consumed draing the period of exclusion.

Rouse Selection:

The vessel sailed along the recommended route.



Speed and Bunker Analysis for Chartered Vessel

(1 of 2)

This calculation is based on the information obtained from the Master/Vessel operator applying allowed time for consumption calculations, it will be updated upon receipt of corrections of Charter Party information or additional data of ship positions, departure/arrival information.

Vessel Name: MANASOTA

WNI Rottle Number: 2007122212 Date: February 16, 2006

ITAGUAL to BEILUN

Performance Speed Evaluation (All Weather)

Distance Sailed	:	1113¢	Miles
Time en Route	:	938.0	Hours
Average Speed	:	11.3	Knot(s)
Weather Factor	:	-0.5	Knot(s)
Current Factor	:	-0.1	Knot(s)
Performance Speed	:	12.5	Knot(s)

						
Voyaga Leg		re 6ROB	: Arrival	BRO8	Bunker Consume	d on Passage
Toyaga Leg	F.O. [MT]	D.C. [MT]	F.O. [MT]	2.O. [MT]	F.O. [Mit]	D.O. IMM
ITAGUAL to SINGAPORE	2013.70	171.BD	22.60	143.50	1891.10	29.30
SINGREORE to BEILTH	2518.00	191.20	2053.70	187.40	464,30	3.80

Notes:

The following time and distance has been excluded from the Performance Speed Evaluation due to transit through Singapore strait:

Date/Time

Duration

Pistance

01/24/06 04002-01/24/08 2000z

16.0 Hours | 100 Milas

The quantity of bunkers consumed on passage excludes 32.80 MT of fuel oil and 12.30 MT of diesel oil that was consumed during the period of exclusion.

Charter Party Terms:

It is understood that the Charter Party Speed is about 14.0 knots on 60.96 M/T fuel oil and 0.51 M/T diesel oil per salling day. Allowing 0.5 knots and 5% consumption for the term 'about', an effective speed of 13.5 knots, 64.01 M/T fuel oil and 0.54 M/T diesel oil have been used in the following calculations.

1. SPEED CALCULATIONS

C/P Speed (-0.5 Knots)	:	13.5 Knot(s)
Weather Factor	;	-0.5 Knot(s)
Current Factor	:	-0.4 Khat(s)

C/P Allowed Speed		12.9 K	no	rt(s)			
Time Allowed	:	11134	,	12.9	<u> </u>	863.1	Hours
ime Losc	:	938.0	-	\$63,1	-	74.9	Hours
	74.9	Hours La	st				 -



Speed and Bunker Analysis for Chartered Vessei

(2 of 2)

This calculation is based on the information obtained from the Mastar/Vessel operator applying allowed time for consumption desculations. If will be undated upon receipt of corrections of Charter Party Information or additional data of ship positions, departure/arrival information.

Vessel Name: MANASOTA

WNI Route Number: 2007;22212. Date: February 18, 2008

2. CONSUMPTION CALCULATIONS

FUEL OIL [MT]

Warranted Consumption (5% upward); 64.01

Calculated Consumption (883.1 / 24 Hours) x 64.01 = 2301.96

Bunker Consumed on Passage 2422.50

Over-consumed 2422,60 - 2301,96 = \$20.64

DIESEL CIL [MT]

Wartanted Consumption (5% upward) :

Calculated Consumption $(363.1 / 24 \text{ Hours}) \times 0.54 =$ 19.42

Bunkar Consumed on Passage 19.80

Over-consumed 19,80 19.42 0.38

Fuel Oil Over-consumed 120.64 Diesei Oil Over-consumed D.39 MT

Report	
Summary	
Voyage	

WNI Route Number: 2007122212 February 12, 2008 Date

23.2S 44.9W December.23, 2007 14:00 (GMT) 1.2N 103.9E January 24, 2008 20:00 (GMT) Tims Enroute 774.0 hours Average Speed: 11.7 knots December.23, 2007 14:00 (GMT) January 24, 2008 20:00 (GMT) Operator: CARDIFF MARINE INC Departure: ITAGUAL Antval: SINGAPORE 9074 miles MANASOTA Distance:

	REPORTED NOON POSITIONS .	O NOON PO	SNOFFIS	DAILY .			8	ANALYZEO WEATNER	ATE OF THE	•	REPORT	REPORTED VESSEL DATA	AVERAGE	46
				• • •			SURFACE WIND	WIND	COMBINE	COMBINED WAYES ENGINE	BNGINE	102 103	٠	ő
DATE	Š	Š	GWI	DISTANCE SPEED	SPEED	E E	SPEED	SPEED BEAUPORY		PRIMARY HEIGHT	RPM	F.O. M.D.D.		W.D.O
				(MW)	(K78)		(KG8)	FORCE	뜅	₹.		(MAT) (MAT)	(Mrs)	CIMI
12/23	23.178	42.00X	14104									2013.70:171.60		•
, \$2/20	35,505	K08-U5	14:00	115.3	33.1	196E	16	÷	SMAL	1.5	2.28	1552.70-171.20	7.73	
32/38	34,668	33. 40N	14:00		2.5	2/2	7.	11	KS3		65.3	1891.40 170.80	<u>.</u>	
32/26	804.6x	28.00X	13100		23.9	<u> </u>	=	#	888	200		1833.50: 170,3D	٠.	
12/27	33,208	21.804	13:00	14	14.0	28813	•		F855	-1	50	3772.60: 169.80		
587	32.503	26.30%	18:00		13.0	¥	ž,	√	K\$8	7.9		1714.20 169.30		<u>:</u> .
67)	31,608	30 40%	12.00	301.0	12.5	. Б	.;;	•	83	. 6.7	85.2	1653, 30 166, Rp		
12/30	31.405	4 10%	12:00		12.7	២	3.6	-	*5	1.0	88.2	3598,40, 168,30	:	
5	34.8115	1.508	13:00	293,0	13,7	888	m	-	¥16	e.	6.20	2534.00 167.8D		
٠.	35.148	4 705	15490.		13.0	388	7	N	8	 	ES. 2	3475.20 162.30	· -	
	25.345	14.102	11,00	332.4	13.0	a		-	iX.	73	H 5. 2	1412.20 166.90	i ·	
	35,305	1G HDZ	10.01		۲. ۲	85	24	io	*	2.3	85.5	1353,30, 166,30	•	
<u>-</u>	35.409	23,305	10,00		r+	2	77	st.	8574		•	1259.60 165.80		
	35.305	208°68	10:00	220.0	9,2:	м	27	ים	388	´⊍ 	15.5	1237,30, 168,30		
3/2	34,508	300-00	8:03	178.1	- 1	Š	31	-	38 28 38 38 38	. 9.2	. BF. 2	1167,00, 164,80		.,
<u>-</u>	32.70g	34,442	9046		9.	丑	2	ব	1888	ري 	95.2	1104,50 764,30	:	· ·
	30,308	35,008			21.5	28	Ξ	¢	95	, 4, 5,	85.3	1042,10, 163.Bd		
	27.705	13 603	8,8	8.000	22.6	'n	11	Δħ	989	1.4	55.2	982.50 163.70		
710	25,603	500.05	120 i B	189.6	12.1	23	ន	4		1.4	85.2	930.00 362.00		
. 21/1	31.768	51.708	00:00	360,7	22.0	le:	2	ч	. 88		85.2	057.00 162.30	63,5	<u>.</u> .
 <u>«</u>	18.605	95.20B	7.00	177.7	12.1	583	2		BSH	1.1	85.2	197.60 161.60	<u>.</u>	
 <u>d</u> :	15,208	51 . TOR	7100	290,4	178.1	努	3.5	÷	K83		83.2	735.10 161.30	2.5	. .
· · ·	13.00\$	62,30E	7,00		18,0	s		N	SE	· F.	63	672.60 160.80		;
1/15	8.708	65.905	4:00	269.4	12.1	288	FI	,	ás	- 	65 65 65	610-101-010	5	
وا	2000	40 300				1							:	


말	82)		AVERAGE	DAILY CONS.									
71222	r 18, 2008				- =-		A 2	2 0	3				9
WNI Route Number: 2007122212	February 18, 2068		REPORTED VESSEL DATA	ROB FD MDD	M/T) (M/T)	407,70,159,30	145-40, 150-69 146 30: 140 10	\$42.60 \$52.80	243, 201, 157, 10	77.80 356.00	137.90 156.36	59.00.185.86	22.68:143.50
WNIR	Date;		REPORTE	NGINE		2.2							
				D WAVES (6	E	6. F					0.0	0.0	
sport			高度	JAFACE WIND COMBINED WAVES GNOINE SPEED BEAUFORT PRIMARY HEIGHT RPM	A.	288 288	1 Kg	- 3	ės	888	20	*16°	
Voyage Summary Report			ANALYZEO WEATHER	No CAUTORT	FORCE	~ ~				- -#	· ·	-1	
Sumn			ANA	SVRFACE WIND SPEED - DEAUS	; (IGTS)	3 3	1 1	us	15	4:	· ф	·	
yage				와.		NELS NAX	£	WEW	820	THE	70	и	
>			.	SPERO	(KT3)	9 77	- 1	32.0	11.9	77.5	10.9	10.01	6.5
			אַזוּאַם	DISTANCE SPERD	(NM) (KTS)	297.1	275.5	266.9	786.1	2013	250.7	208.6	20.0
			SNOIL	GAT			5:00	5:00	2:00	2:00	00.4	. P0.	40:00
			NOOM POS	NO.	. 4	78.5482. 78.548	12.425°	86.048	91.108	99.50E	69.20E	102,500	103.914
			REPORTED NOON POSITIONS	3		1.306	0.60%	3,632	4.500	6.300			1.328
		MV madmicus	٠.	. DATE		1/10	- π/π-	02/7	1/21	1/23	.3723	1/24	1/24


Document 17-3


Page 19 of 27


Filed 04/28/2008

Case 1:08-cv-01804-PAC









MANASCYA Operator: CARDIFF MARINE INC	WW Route Number: 2007/22212	Date: February 18, 2008			98 15:00 (GMT) 08 03:00 (GMT) 8 Speed; 12.0 knots		SNED WAVES ENGINE ROS DARY DARY DARY DARY DARY DARY DARY DARY	(WIT) (WIT)	3513.00 191.20		2.50	1.3 \$5.2. 2256.69 189.60 67.5	1.6 85.2 2239.19 141.97 (2.5	3.6 65.2 23.75.19 189.40 61.0°	65.2, 2212.19 367.00 61.0°	2059-7P, 187-4P 61.P; 0.5	•	 			 		
MANASO; Departure; Arrival; Distance; LAT LON LAT LON 1.25N 105.008 3.54W 105.508 7.50W 105.508 8.550W 105.508 10.250W 112.508 20.250W 122.608	 Voyage Summary Repo			!	SINGAPORG 1.2N BEILUN 30.6N 2160 miles Time Enu	A IIVO	SURFACE WIND SURFACE WIND DISTANCE SPEED DISTANCE OF STATES	(MM) (KTS) (KTS) FORCE	TAN 1 C 0.841	317.5 13.0 8NS 18 5	263.6 11.0 NRF 16 4	275.9 11.5 BNG 14 a	374.4 21.4 10: 16 4	276.8 11.5 NF 32 7	266.7 11.1 NWE 23 6	0.17.0							
· · · · · · · · · · · · · · · · · · ·			Will orangement	MANASO	Departuro; Arrival; Distanco;	PEPORTED NOON PO	tai tok																

NE 1.L

NE 1,⊕

Z7 6≅a,a

20N

31. . NNE 4 I

